

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 4/27/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S03UU_015MH

Test ID: D1032-022012

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S03UU_015MH
0			Water Level	
2			Dye Test Visible	@ B, 0.25gpm
5.099999905			Dye Test Visible	@ IR, 0.25gpm
7			Dye Test Visible	@ TF IR, 1gpm
12.80000019			Dye Test Visible	@ IR, < 0.1gpm
20.10000038			Abandoned Survey	NO MORE DYE VISIBLE